

There are few places that are mentioned in the report but are not in the list of communities mentioned in the U.S. Census. 2010.

The erosion status of these communities are given below:

Place or Area	Erosion Code (by ISER)	Erosion Code Explanation
Circle View-Stampede Estates	2	Monitor Conditions Communities. Problems are significant and conditions should be monitored.
Pile Bay-Williamsport	2	Monitor Conditions Communities. Problems are significant and conditions should be monitored.
Chignik Bay	3	Minimal Erosion Communities. Problems are minimal.
Portage	3	Minimal Erosion Communities. Problems are minimal.
Upper Chena	3	Minimal Erosion Communities. Problems are minimal.

Source:

U.S. Army Corps of Engineers. Alaska District. Study Findings and Technical Report: Alaska Baseline Erosion Assessment. March 2009.

<http://www.poa.usace.army.mil/Portals/34/docs/civilworks/BEA/AlaskaBaselineErosionAssessmentBEAMainReport.pdf>